



# Base Pressure

Turns of Base Pressure	1/4	1/2	3/4	1	1.25	1.5	1.75	2	2.25	2.5	2.75	3
	124	174	224	274	324	374	424	474	524	574	624	674
Turns of Base Pressure	3.25	3.5	3.75	4	4.25	4.5	4.75	5				
	724	774	824	874	924	974	1024	1074				